

BOXER PLUS

CLEANING BOXER PLUS AFTER CHIMNEY SWEEP

1.



Boxer Plus cut through

2.



Remove both reflection shields (1. and 2.) by lifting and tilting. Please be care full for damage.

3.



4.



Use a vacuum cleaner to remove soot residue from the top reflection shield...

5.



6.



...or remove the bar on which the top reflection shield rests and let the soot residue slide of.